


A

No.	Código	Clave	Descripción
1	945043	R1-CARBA-50X	Tapón de manija
1.1	945044	R1.1-CARBA-50X	Tornillo phillips ST 4x8
2	945045	R2-CARBA-50X	Manija de correa
3	945046	R3-CARBA-50X	Soporte de manija
3.1	945047	R3.1-CARBA-50X	Tornillo phillips ST4x10
4	945048	R4-CARBA-50X	Cubierta
5	945049	R5-CARBA-50X	Tarjeta panel
5.2	945051	R5.2-CARBA-50X	Tuerca plástica ST4x8
5.3	945052	R5.3-CARBA-50X	Buje 4x7x3
6	945053	R6-CARBA-50X	Placa de enfriamiento
6.1	945054	R6.1-CARBA-50X	Tornillo phillips con arandela
6.2	945055	R6.2-CARBA-50X	Tuerca M3
6.3	945056	R6.3-CARBA-50X	Soporte
6.4	945057	R6.4-CARBA-50X	Tuerca con arandela M5
6.5	945058	R6.5-CARBA-50X	Tornillo phillips M5x10
7	945059	R7-CARBA-50X	Soporte de placa
7.2	945061	R7.2-CARBA-50X	Tornillo phillips ST4x12.5
8	945062	R8-CARBA-50X	Tarjeta principal
8.1	945063	R8.1-CARBA-50X	Arnés maestro
9	945064	R9-CARBA-50X	Transformador
9.2	945066	R9.2-CARBA-50X	Arandela Ø5.5
10	945068	R10-CARBA-50X	Placa deflectora
10.1	945069	R10.1-CARBA-50X	Tornillo phillips ST5x20
11	945070	R11-CARBA-50X	Placa leteral
11.1	945071	R11.1-CARBA-50X	Tornillo phillips ST2x10
12	945072	R12-CARBA-50X	Base
13	945073	R13-CARBA-50X	Fijador de tensión
13.1	945074	R13.1-CARBA-50X	Tornillo phillips ST3x16
13.2	945075	R13.2-CARBA-50X	Protector de cable




A



B

No.	Código	Clave	Descripción
14	945076	R14-CARBA-50X	Pinza polo positivo
14.1	945077	R14.1-CARBA-50X	Tornillo phillips M6x12
14.2	945078	R14.2-CARBA-50X	Arandela Ø6.5
14.3	945079	R14.3-CARBA-50X	Tuerca M6
15	945080	R15-CARBA-50X	Cable polo positivo para pinza
16	945081	R16-CARBA-50X	Pinza polo negativo
17	945082	R17-CARBA-50X	Cable polo negativo para pinza
18	945083	R18-CARBA-50X	Pata
19	945085	R19-CARBA-50X	Opresor de cable
19.1	945086	R19.1-CARBA-50X	Tornillo phillips ST3x12 3x12
20	945087	R20-CARBA-50X	Cable de alimentación
20.1	945088	R20.1-CARBA-50X	Tornillo phillips M4x14
20.2	945089	R20.2-CARBA-50X	Tuerca M4
20.3	945090	R20.3-CARBA-50X	Arandela de presión M4.5
20.4	945091	R20.4-CARBA-50X	Arandela plana M4.5
20.5	945092	R20.5-CARBA-50X	Arandela de seguridad M4.5
21	945093	R21-CARBA-50X	Tornillo phillips M6x35
21.2	945095	R21.2-BOS-3/4LH	Arandela plana M6.5
21.3	945096	R21.3-CARBA-50X	Arandela de presión M6.5
22	945097	R22-CARBA-50X	Porta fusibles 1
23	945098	R23-CARBA-50X	Porta fusibles 2
24	945099	R24-CARBA-50X	Fusible 80A
25	945100	R25-CARBA-50X	Cubierta de fusible
26	945101	R26-CARBA-50X	Ventilador DC 5V
27	945102	R27-CARBA-50X	Soporte de ventilador
27.1	945103	R27.1-CARBA-50X	Tornillo phillips M4x8
27.3	945105	R27.3-CARBA-50X	Tornillo phillips ST4x12



B

